PCT/EP02/06400




Fig. 1

PCT/EP02/06400

2/7




Fig. 2




Fig. 3





Fig. 4



. #

6/7




Fig. 6

7/7

2 11

11

Lxer	n1 = 2	n2 = 1	n3 = 5
Slave mixer	q1 = 2	q2 = 5	q3 = 4
	H	4	7
nixer	다	:2 =	ب 5 اا
Master mixer	S1 = 2	S2 := 4	s3 = 5

	1	5//	2
3	2	9	3
4	3	7	4
ហ	4	8	5
9	S	6	9
7	9	10	7
8	7	11	8
6	8	12	6

Fig. 7